

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**







































































BY DETECTO

TO OPERATE:

1. ATTACH SLING
2. PRESS ON KEY
3. PRESS ZERO KEY
4. LIFT PATIENT
5. PRESS LOCK KEY
6. LOWER PATIENT
7. READ WEIGHT



lb

LOCK

LOCK
UNLOCK

UNITS


ZERO

ON
OFF

Reliant Scale

MODEL RLS6

CAPACITY 600 lb, 272 kg



















7. NAME (LAST, FIRST, MIDDLE)
8. ADDRESS
9. CITY, STATE, ZIP
10. PHONE NUMBER
11. DATE OF BIRTH
12. SEX
13. OCCUPATION
14. EDUCATION
15. MARITAL STATUS
16. CHILDREN
17. SIGNATURE
18. DATE


19. COMMENTS



























WARNING
Do not touch the hot surface of the engine or its components. The engine and its components may become very hot during operation. Touching the hot surface of the engine or its components may result in serious injury or death.
Do not touch the hot surface of the engine or its components. The engine and its components may become very hot during operation. Touching the hot surface of the engine or its components may result in serious injury or death.
Do not touch the hot surface of the engine or its components. The engine and its components may become very hot during operation. Touching the hot surface of the engine or its components may result in serious injury or death.



WARNING
No support assemblies must be
fastened to the bed frame BEFORE
use, injury or damage may result.
Rev. A (11-25-90) P/N 1003324

